5PE.5605

Official Eligibility Determination

OAHP1403 Rev. 9/98

COLORADO CULTURAL RESOURCE SURVEY

Architectural Inventory Form

Page 1

Date Initials

- _Determined Eligible-National Register
- _Determined Not Eligible National Register
- _Determined Eligible State Register
- _Determined Not Eligible State Register
- _Need Data

(OAHP use only)

- Contributing to eligible National Register District
- _Noncontributing to eligible National Register District



I. IDENTIFICATION

1.	Resource number:	5PE.5605		Parcel number(s):				
2.	Temporary resource number:	027		525418009				
3.	County:	Pueblo						
4.	City:	Pueblo	Pueblo					
5.	Historic building name:	Wells, R.H., House	Nells, R.H., House					
6.	Current building name:	Gonzales, Lee, Apar	Gonzales, Lee, Apartments					
7.	Building address:	419-421 W 12th Street						
8.	Owner name:	Lee Gonzales Trust						
	Owner organization:							
	Owner address:	PO Box 2242						
		Pueblo, CO 81004						
44.	National Register eligibility field	assessment:	Individually eligible	Not eligible	Need data			
	Local landmark eligibility field a	ssessment:	Individually eligible	Not eligible	Need data			

Sorted by Resource Number

Architectural Inventory Form

Page 2

II. GEOGRAPHIC INFORMATION

9.	P.M.:	6t	h			Towr	nship	: 2	20S			Ra	nge:	65W	I
	Ν	NE	1/4	of	SE	1/4	of	NW	1/4	of	SE	1/4	of Sec	tion	25
10.	UTM re	ferei	nce zo	ne:	1	3									
	Easting	:			5	33923						Northin	g:		4236537
11.	USGS of	quad	Iname	e :	Ν	lorthe	ast P	Pueblo	I.			Scale:			7.5
	Year:					961 (P 974)	hoto	orevise	ed 197	0 and	I				
12.	Lot(s) :				L	ot 11;	Blog	ck 26							
	Additior	า:			С	ounty	Add	lition				Year of	addition	n:	1869

13. Boundary description and justification:

The boundary, as described above, contains but does not exceed the land historically associated with this property.

Metes and bounds exist:

П

III. ARCHITECTURAL DESCRIPTION

14.	Building plan (footprint, shape):	Irregular Plan	
	Other building plan descriptions:		
15.	Dimensions in feet (length x width):	1,560 square feet	
16.	Number of stories:	2	
17.	Primary external wall material(s):	Stucco	Other wall materials:
		Wood/Shingle	
18.	Roof configuration:	Shed Roof	
	Other roof configurations:		
19.	Primary external roof material:	Asphalt Roof/Composition Roof	
	Other roof materials:		
20.	Special features:	Fence	
		Chimney	
		Balcony	
		Porch	

21. General architectural description:

Oriented to the south, this apartment building rests on a random-coursed sandstone foundation, covered in white-painted stucco. Rough-textured, white-painted stucco also clads the exterior walls. White-painted wood shingles cover a small, singlestory, shed-roofed addition on the east elevation. Windows are 1-over-1-light, double-hung sash, with white-vinyl frames and surrounds. A two-story, hipped-roof porch spans the entire front (south) facade. The porch features wood Tuscan columns and white-painted, flakeboard kneewalls. Screens enclose the upper story. A pair of 4-step concrete stoops approach the porch from near its east and west sides. Two doorways, offset west of center on the nearly symmetrical facade, open beneath the porch. Both are identical and host 15-light, glass-in-wood-frame doors, painted white, opening behind white, aluminum-frame storm doors. Surrounding the doors are sidelights and a transom, with green-painted wood frames and surrounds. A gray, six-panel door on the east end of the porch provides access to an interior staircase. A two-story, shed-roof porch emerges from the center of the rear (north) elevation. Four doors, two on each floor, open from the porch. Both are white-painted, single-light, opening behind white, aluminum-frame storm doors. The doors in the second story provide access to a single, white-painted, wood staircase, descending to the north. Gray, rolled asphalt sheets cover the shed roof, which is surrounded by a parapet. The rafter ends of the front (south) porch roof are exposed, but capped by a fascia board. A white, stucco-clad chimney

Sorted by Resource Number

Architectural Inventory Form

Page 3

protrudes from the northeast corner of the roof.

22. Architectural style:

No Style

Other architectural styles:

Building type:

23. Landscape or special setting features:

This property is located on terrain sloping downward from north to south, with an elevation of around 4,700 feet above mean sea level. The neighborhood features modest, one- and two-story houses. This property is located on the north side of West 12th Street, an east-west-oriented thoroughfare. It is situated between 417 West 12th Street, to the east, and 425 West 12th Street, to the west. A gravel-covered strip separates the sidewalk from the street. Concrete slabs, interrupted by three planters, cover the area between the sidewalk and the building. Gravel covers the entire yard. A chain-link fence encircles the backyard.

24. Associated buildings, features or objects:

1:	Туре:	Garage
	Describe:	A garage is located north of the house, accessed from the east-west alley along the north edge of the property. Oriented to the north, the building appears to lack a formal foundation. It consists of 2 district halves, with the east half protruding northward farther than the west half. Green-blue-painted particleboard sheets clad the exterior walls. The front (north) elevations of both halves host sliding, blue-green-painted, beadboard doors. A small plank door opens in the east end of the front (north) elevation. Sheets of gray, rolled asphalt cover the shed roof and parapet.

IV. ARCHITECTURAL HISTORY

25.	Date of Construction:	Estimate:	1885 (origina	Actual:
	Source of Information:	Pueblo Cour	nty Office of Tax	Assessor. Property information card [internet].
26.	Architect:	unknown		
	Source of information:			
27.	Builder:	unknown		
	Source of information:			
28.	Original Owner:	R.H. Wells		
	Source of information:			

29. Construction history:

According to Pueblo County tax records, this building was constructed in 1900. However, city directories and Sanborn insurance maps reveal that this building existed around 1885. The original building was a single-family home. It consisted of an L-shaped plan, with the inside corner facing northeast. Around 1920, an owner filled the inside corner of the L to create the current apartment building. Based on Sanborn maps, the porch and much of the façade are elements relatively unchanged from the 1885 house. The current apartment building, however, is largely of 1920s vintage. The most notable alteration since that time has been the application of stucco over the original masonry walls.

30. Location: original Date of move(s):

V. HISTORICAL ASSOCIATIONS

31.	Original use(s):	Single Dwelling
32.	Intermediate use(s):	Multiple Dwelling
33.	Current use(s):	Single Dwelling
34.	Site type(s):	Apartments

35. Historical background:

Originally addressed 421 West 12th Street, this house was a single-family home constructed for architect R.H. Wells. By 1900,

Page 4

the residents were Logan and Mamie Ragle, who lived here with daughters Amy and Margerty. Logan was a real estate broker for E. Brayton. Also living here was Benjamin S. Wolf, a motorman for the Pueblo Traction & Electric Company. Other residents were Alexander Mack (circa 1914) and A.S. MacKinnon (circa 1919).

Benjamin Wolfe purchased the property outright between 1920 and 1925, the same period during which this single-family residence became a four-unit apartment building. A sampling of residents is listed below by address:

419 (East Side, First Floor): John Jaynes Ryan (circa 1925); John Power (circa 1930); Amy A Philbin (circa 1935); Ralph H. Koehler (circa 1940); Charles Hindes (circa 1950); Lennis Nichols (circa 1960).

419 1/2 (East Side, Second Floor): J.H. Keesee (circa 1925); Anthony J. Sarconi (circa 1930); Josephine Rupp (circa 1940); Richard B. Gordon (circa 1945); Jack Hamilton (circa 1950); Harry A Babnick (circa 1955); Mae S. Spears (circa 1960).

421 (West Side, First Floor): V.P. Price (circa 1925); Anna Ryan (circa 1935); Benjamin Wolf and Agnes A. Watkins (circa 1940); Bina Stroh and Beulah Ehler (circa 1945); Gerald G. Garman (circa 1950); Jewett Seaman (circa 1955); Don T. Chulick (circa 1960).

412 1/2 (West Side, Second Floor): William J. Stahl (circa 1930); Paul Christensen (circa 1940); Christian M. Prior (circa 1945); Jack W. Bauer (circa 1950); Melvin C. McGee, Jr., (circa 1955).

Lee and Senorina A. Gonzales purchased this property in 1979, transferring it into the Lee Gonzales Trust, the current owner, in 1998. It continues to operate as a 4-unit apartment building.

36. Sources of information:

Pueblo County Office of Tax Assessor. Property information card [internet].

Pueblo City Directory. Pueblo, Co.; Salt Lake City; Kansas City, Mo.; and others: R.L. Polk & Co, consulted 1886 through 2003.

U.S. Census of 1900. Precinct 1, Pueblo, Pueblo County, Colorado. Series T623, roll 128, p. 20.

Sorted by Resource Number

Architectural Inventory Form

Page 5

	č
VI. S	IGNIFICANCE
37.	Local landmark designation: Yes 🔲 No 🔽
	Designation authority:
	Date of designation:
38.	Applicable National Register criteria:
	A. Associated with events that have made a significant contribution to the broad pattern of our history.
	 A. Associated with events that have made a significant contribution to the bload pattern of our history. B. Associated with the lives of persons significant in our past.
	C. Embodies the distinctive characteristics of a type, period, or method of construction, or represents the work of a master, or that possess high artistic values, or represents a significant and distinguished entity whose
	components may lack individual distinction.
	 D. Has yielded, or may be likely to yield, information important in history or prehistory. Qualifies under Criteria Considerations A through G (see manual).
	Does not meet any of the above National Register criteria.
	Pueblo Standards for Designation:
	1a. History
	Have direct association with the historical development of the city, state, or nation; or
	<u>1b. History</u>
	Be the site of a significant historic event; or
	1c. History
	Have direct and substantial association with a person or group of persons who had influence on society.
	2a. Architecture
	Embody distinguishing characteristics of an architectural style or type; or
	2b. Architecture
	Be a significant example of the work of a recognized architect or master builder, or
	 <u>2c. Architecture</u> Contain elements of architectural design, engineering, materials, craftsmanship, or artistic merit which represent a
	significant or influential innovation;
	2d. Architecture Partray the environment of a group of people or physical development of an area of the city in an era of history
	Portray the environment of a group of people or physical development of an area of the city in an era of history characterized by a distinctive architectural style.
	3a. Geography
	Have a prominent location or be an established, familiar, and orienting visual feature of the contemporary city, or
	<u>3b. Geography</u>
	Promote understanding and appreciation of Pueblo's environment by means of distinctive physical characteristics or rarity; or
	<u>3c. Geography</u>
	Make a special contribution to Pueblo's distinctive character.
	Not Applicable
	Does not meet any of the above Pueblo landmark criteria.
39.	Area(s) of Significance: Not Applicable
40.	Period of Significance: n/a
41.	Level of significance: National: 🖸 State 🗖 Local 🗖

Page 6

42. Statement of significance:

This property is historically significant under Pueblo Local Landmark criterion 1A for its association with the development of Pueblo's North Side Neighborhood. It represents the conversion of many single-family homes into apartments during the 1920s and 1930s, reflecting a downturn in the economy. However, the levels of architectural and historical significance, combined with physical integrity, are not to the extent that this property would qualify for individual listing in the National Register of Historic Places, the Colorado State Register of Historic Properties, or as a City of Pueblo Landmark. Nonetheless, it is a contributing resource within any potential historic district.

43. Assessment of historic physical integrity related to significance:

Reconstructed around 1920, the principal building on this property exhibits a moderately high level of physical integrity relative to the seven aspects of integrity as defined by the National Park Service and the Colorado Historical Society: location, setting, design, materials, workmanship, feeling, and association. The most notable alteration has been the application of stucco over the original masonry.

VII. NATIONAL REGISTER ELIGIBILITY ASSESSMENT

44.	National Re	Individually eligible			Not eligible	Need data	
	Local landm	ark eligibility field assessment:		ndividual	y eligible	Not eligible	Need data
45.	Is there Nat	ional Register district potential?	Yes 🛃	No			
	Discuss:				the city's professional middle represents the city's changing		

classes. Its diversity of architectural styles and forms directly represents the city's changing economic and cultural climates. As well, the neighborhood is distinctive because it appears to have evolved independently of the area's dominant industry, steel manufacturing.

Yes

Yes

No

No

N/A

N/A


If there is National Register district potential, is this building contributing:

46. If the building is in existing National Register district, is it contributing:

VIII. RECORDING INFORMATION


47.	Photograph numbers):	CD-ROM Photo Disc: North Side Photos File Name(s): 12thstw419-421
	Negatives filed at:	Special Collections Robert Hoag Rawlings Public Library 100 East Abriendo Avenue Pueblo, CO 81004-4290
48.	Report title:	Pueblo North Side Neighborhood Survey
49.	Date(s):	06/13/2005
50.	Recorder(s):	Adam Thomas
51.	Organization:	Historitecture, L.L.C.
52.	Address:	PO Box 419
		Estes Park, CO 80517-0419
53.	Phone number(s):	(970) 586-1165

Page 7



Page 8

LOCATION MAP



Source: U.S. Geological Survey 7.5' Northeast Pueblo topographic quadrangle - 1961 (Photorevised 1970 and 1974)