COLORADO CULTURAL RESOURCE SURVEY

Architectural Inventory Form

Page 1

,	(C) (The Coc Only)
[Date Initials
	Determined Eligible-National Register
_	Determined Not Eligible - National Register
_	Determined Eligible - State Register
-	Determined Not Eligible - State Register
_	Need Data
_	Contributing to eligible National Register District
	Name and the street and all other National Desires and District



I. IDENTIFICATION

Resource number: 5PE.5617 Parcel number(s):
Temporary resource number: 044 525420009

County: Pueblo
 City: Pueblo

5. Historic building name: Clanton-Stilwell House

6. Current building name: Klipfel, Charles H., IV, and Jennifer H., House

7. Building address: 613 W 12th Street

8. Owner name: Charles H. Klipfel, IV, and Jennifer H. Klipfel

Owner organization:

Owner address: 613 W 12th St

Pueblo, CO 81006

44.	National Register eligibility field assessment:	Individually eligible	Not eligible	☐ Need data
	Local landmark eligibility field assessment:	Individually eligible	Not eligible	■ Need data

613 W 12th Street 5PE.5617

(Resource number)

Architectural Inventory Form

Page 2

II. G	ЭE	OGR	AP	HIC IN	NFOF	RMA	TION	I								
9.		P.M.:	(6th			Tow	nship:	: :	20S				Range:	65V	N
			NE	1/4	of	sw	1/4	of	NW	1/4	of	SE	1/4	of S	Section	25
10).	UTM	refer	ence z	one:	1	3									
		Eastir	ng:			5	33687	7					Nort	hing:		4236544
11	11. USGS quad name: Northeast Pt				ueblo)			Scal	le:		7.5				
	Year: 1961 (Photor 1974)							revis	ed 197	70 and	d					
12	2.	Lot(s)):			L	ot 13	; Bloc	k 42							
		Additi	ion:			C	County	y Add	ition				Year	r of addit	ion:	1869
13.		Bound	dary	descrip	ption a	nd jus	tificati	ion:								
		The p	arce	el, as d	lescril	oed ak	oove,	conta	ins b	ut doe	es not	t exce	ed the	land his	torical	ly associated with this property.
		Mete	es an	d boun	nds exi	st:										
	A D		TEO	TUD	A. D	F00	DIDT	'ION								
				TUR				ION								
14.			•	lan (foc		•	•		T-8	Shape	d Plai	n				
				ding pla												
15.				ns in fe	•	gth x v	width)	:		72 sq	uare f	feet				
16.		Number of stories:					1									
17.	. Primary external wall material(s):					Stı	ıcco					Other wall materials:				
18.		Roof (confi	guratio	n:				Ga	bled F	Roof/0	Cross	Gable	d Roof		
		Other	roof	config	uratio	ns:										
19.		Prima	ary ex	xternal	roof m	nateria	ıl:		As	phalt l	Roof/	Comp	osition	Roof		
		Other	roof	materi	ials:											
20.		Speci	ial fe	atures:					Fe	nce						
21.		Gene	ral a	rchitect	tural d	escrip	tion:									
		rests hung west also lexten cente frame proje	on a sas elev has a ds a er in e sto cting	a tan-ti h, with ations a singl across the oth rm doo g from	inted, brow are 1- le-ligh most herwistor. Ar	stucce n-pair beside t case of the se syn netal a	o-cov nted v le-1-light ement e prince nmetr awnin	ered f wood ght, s wind cipal (ical fa ng, wh	found frame liding low. T (soutl açade nite w ar (no	lation. es and g-sash They o h) faça e. The with 2 b orth) el	The standard The s	same ninum dows, penea t prov way he n strip on. It	stucco n-frame with al th segn ides ac osts a t es, pro hosts a	o clads the storm when the storm whe	he exte vindow frame rches. / the pri t, wood e doorv lentical	acing south, toward the street. The building brior walls. Windows are 1-over-1-light, double-is. Opening on the north ends of the east and s. The west end of the rear (north) elevation A single-step, uncovered concrete stoop ncipal doorway, which opens just east of I slab door, opening behind an aluminumway. Another doorway opens into a room I to the front (south). Brown-gray asphalt the eaves.
22.		Archit	tectu	ral styl	e:				O	ther S	tyle					
		Other	arch	nitectur	al styl	es:			Fr	ont-G	abled	l, Mas	onry B	ох		
		Buildi	ng ty	pe:												
23.		Lands	scape	e or sp	ecial s	etting	featu	res:								

613 W 12th Street 5PE.5617
(Resource number)

Architectural Inventory Form

Page 3

This property is located on terrain sloping downward from north to south, with an elevation of around 4,700 feet above mean sea level. The neighborhood features modest, one- and two-story houses. This property is located on the north side of West 12th Street, an east-west-oriented thoroughfare. It is situated between 607 West 12th Street, to the east, and 619 West 12th Street, to the west. A grass strip separates the sidewalk from the street. Surrounding the house is a planted-grass yard, with mature landscaping. A wood privacy fence encloses the entire back yard.

24. Associated buildings, features or objects:

1: Type: Shed

Describe: A small, prefabricated metal storage shed is located on the north edge of the property.

However, because of the inaccessibility to the property, it was not surveyed.

IV. ARCHITECTURAL HISTORY

25. Date of Construction: Estimate: 1885 Actual:

Source of Information: Pueblo City Directory. Pueblo, Co.; Salt Lake City; Kansas City, Mo.; and others: R.L. Polk &

Co, consulted 1886 through 2003.

Sanborn Fire Insurance Maps (for Pueblo, Colorado). New York: Sanborn Map and

Publishing Co., 1883, 1886, 1889, 1893, 1904-05, 1904-51, and 1904-52.

26. Architect: unknown

Source of information: Pueblo County Office of Tax Assessor. Property information card [internet].

27. Builder: unknown

Source of information:

28. Original Owner: unknown

Source of information:

29. Construction history:

According to Pueblo County tax records, this building was constructed in 1900. However, city directories and Sanborn insurance maps suggest that this building existed around 1885. An analysis of the form, style, and materials corroborates a circa 1885 date of construction. The most notable alteration has been the application of stucco over the original masonry. This stucco was either originally applied or recoated sometime after 2000. Some windows and doors have also been replaced, the earliest dating to the 1970s. A small, shed-roofed porch protruding from the rear elevation was enclosed at an unknown date.

30. Location: **original** Date of move(s):

V. HISTORICAL ASSOCIATIONS

31. Original use(s): Single Dwelling
32. Intermediate use(s): Single Dwelling
33. Current use(s): Single Dwelling

34. Site type(s): Residence

35. Historical background:

This house dates to at least 1890, when W. Clanton, a boilermaker, and Charles Stilwell, a machinist, lived here. By 1900, the owner and resident was William E. Klasgye, an engineer for the Atchison, Topeka and Santa Fe Railway. He was born in October 1849 in Ohio. He wife, Sarah M. Klasgye, was born in England in 1866. They were married around 1888 and had at least four children.

By 1909, the owner and resident was Flora A. Peck, whose family would reside here for at least the next 2 decades. She was born in New Mexico in 1851 and had at least one daughter, Helen E. Peck. Around 1912, Helen married Edward Nasson and, circa 1915, moved to this address to reside with Flora Peck. Edward and Helen Nasson had at least three children: Flora, Jack, and Raymon. Young Flora Nasson married William H. Decker and they, too, became residents of this house, around 1930. They remained here until before 1935. Flora Nasson Decker died on February 20, 1961. William, an automobile mechanic, died on

613 W 12th Street 5PE.5617

(Resource number)

Architectural Inventory Form

Page 4

September 27, 1968.

Around 1935, the resident was Roy G. Warmoth. Herman L. Bryan and his wife, Bessie Bryan, lived at this address around 1940. Together, the Bryans had four children: Rev. Charles William Bryan, Mrs. Harry McDowell, Mrs. Robert Cardwell, Mrs. Ray Schultze, and Mrs. William Pyle. The Bryans resided here only a few years, later moving to 1266 South Emerson. Herman Bryan died in September 1969.

Around 1945, the owner was William Russell Manka, who resided here for a decade, until his death in 1955. Manka lived here with his wife, Nellie Manka. Together, they had three children: Georgia Lou Timme, John R. Manka, and Jerry Lee Manka. William Manka was an electrician for Colorado Fuel & Iron. He was killed as a result of a workplace accident in September 1955.

Purchasing this property following Manka's death was Clifford I. Chaddick, whose family would reside here for nearly 4 decades. He was born on January 2, 1916, in Francis, Oklahoma. On January 3, 1940, Chaddick married his wife, Mary J. Together, they had three children: Chad Chaddick, Clifford L. Chaddick, and Margaret Crandall. In 1950, Clifford and Mary Chaddick moved from Oklahoma to Pueblo. The elder Clifford Chaddick was a conductor for the Denver & Rio Grande Western Railroad. He was local chairman for the railroad's grievance committee and was secretary of the United Transportation Union, Lodge 204. The Chaddick family attended the Broadway and Orman Church of Christ. The elder Clifford Chaddick died on November 12, 1973. Mary continued to own this property until her own death on November 18, 2000. Mary's estate transferred the property to her daughter, Margaret (Crandall) Fuller. Fuller, in turn, sold the property to C.H. Klipfel, IV, and J.N. Klipfel, the current owners, in 2001.

36. Sources of information:

Pueblo City Directory. Pueblo, Co.; Salt Lake City; Kansas City, Mo.; and others: R.L. Polk & Co, consulted 1886 through 2003.

"Clifford I. Chaddick" obituary. Pueblo Chieftain, 13 November 1973, p. 5B.

"Manka (William Russell)" obituary. Pueblo Chieftain, 28 August 1955, p. 5B.

"Decker (William H.)" obituary. Pueblo Chieftain, 28 September 1968, p. 7A.

"Bryan (Herman L.)" obituary. Pueblo Chieftain, 27 September 1969, p. 15A.

U.S. Census of 1900. Precinct 1, Pueblo, Pueblo County, Colorado. Series T623, roll 129, p. 10.

U.S. Census of 1910. Precinct 3, Pueblo, Pueblo County, Colorado. Series T625, roll 170, p. 140-1.

5PE.5617

Architectural Inventory Form

Page 5

VI.	SIGNIFICANCE										
37	Local landmark designation: Yes NoDesignation authority:										
	Date of designation:										
38	3. Applicable National Register criteria:										
	 A. Associated with events that have made a significant contribution to the broad pattern of our history. B. Associated with the lives of persons significant in our past. C. Embodies the distinctive characteristics of a type, period, or method of construction, or represents the work of a master, or that possess high artistic values, or represents a significant and distinguished entity whose components may lack individual distinction. D. Has yielded, or may be likely to yield, information important in history or prehistory. Qualifies under Criteria Considerations A through G (see manual). Does not meet any of the above National Register criteria. 										
	Pueblo Standards for Designation:										
	 1a. History Have direct association with the historical development of the city, state, or nation; or 1b. History Be the site of a significant historic event; or 1c. History Have direct and substantial association with a person or group of persons who had influence on society. 2a. Architecture 										
	Embody distinguishing characteristics of an architectural style or type; or										
	 2b. Architecture Be a significant example of the work of a recognized architect or master builder, or 2c. Architecture Contain elements of architectural design, engineering, materials, craftsmanship, or artistic merit which represent a 										
	Contain elements of architectural design, engineering, materials, craftsmanship, or artistic merit which represent a significant or influential innovation; 2d. Architecture										
	Portray the environment of a group of people or physical development of an area of the city in an era of history characterized by a distinctive architectural style.										
	3a. Geography Have a prominent location or be an established, familiar, and orienting visual feature of the contemporary city, or 3b. Geography										
	3b. Geography Promote understanding and appreciation of Pueblo's environment by means of distinctive physical characteristics or rarity; or										
	3c. Geography Make a special contribution to Pueblo's distinctive character.										
	Not Applicable Does not meet any of the above Pueblo landmark criteria.										
3	9. Area(s) of Significance: Architecture										
	0. Period of Significance: Architecture, ca. 1885										
	1. Level of significance: National: State Local										

613 W 12th Street 5PE.5617

(Resource number)

Architectural Inventory Form

Page 6

42. Statement of significance:

This property is historically significant under Pueblo Local Landmark criterion 1A for its association with the initial development of Pueblo's North Side Neighborhood. This house was one of the earliest dwellings constructed in this neighborhood. As well, the house is architecturally significant under National Register criterion C (Pueblo Local Landmark criterion 2A) as an intact example of a front-gabled, masonry form once common to the area and among the earliest domiciles constructed in this neighborhood. However, the levels of architectural and historical significance, combined with physical integrity, are not to the extent that this property would qualify for individual listing in the National Register of Historic Places, the Colorado State Register of Historic Properties, or as a City of Pueblo Landmark. Nonetheless, it is most likely a contributing resource within any potential historic district.

43. Assessment of historic physical integrity related to significance:

Constructed around 1885, this building exhibits a moderate level of physical integrity relative to the seven aspects of integrity as defined by the National Park Service and the Colorado Historical Society: location, setting, design, materials, workmanship, feeling, and association. While the building has had no major additions, the application of stucco over the original masonry obscures a character-defining feature. Nonetheless, the building retains sufficient physical integrity to convey its significance.

II. I	IANOITAN	L REGISTER ELIGIBILITY AS	SSESS	MEN	Т											
44.	National Re	egister eligibility field assessment:		☐ Indi	ividually	eligible		Z) N	ot eli	gible			leed d	lata		
	Local landn	nark eligibility field assessment:		☐ Ind	lividually	/ eligible	Not eligible					■ Need data				
45.	Is there Na	tional Register district potential?	Yes		No											
	Discuss:	Pueblo's North Side Neighborho classes. Its diversity of architect cultural climates. As well, the net the area's dominant industry, steps	ural styl ighborh	es and	d forms disting	directly re	presen	ts the	city	's ch	angin	g eco	nomi	c and		
	If there is N	lational Register district potential, is t	his buildi	ing con	ntributin	g:	Yes		No		N/A					
46.	If the building	ng is in existing National Register dis	trict, is it	contrib	outing:		Yes		No		N/A	7				

VIII. RECORDING INFORMATION

47. Photograph numbers): CD-ROM Photo Disc: North Side Photos

File Name(s): 12thstw613

Negatives filed at: Special Collections

Robert Hoag Rawlings Public Library

100 East Abriendo Avenue Pueblo, CO 81004-4290

48. Report title: Pueblo North Side Neighborhood Survey

49. Date(s): 06/15/200550. Recorder(s): Adam Thomas

51. Organization: Historitecture, L.L.C.

52. Address: **PO Box 419**


Estes Park, CO 80517-0419

53. Phone number(s): (970) 586-1165

613 W 12th Street 5PE.5617
(Resource number)

Architectural Inventory Form

Page 7




613 W 12th Street 5PE.5617
(Resource number)

Architectural Inventory Form

Page 8

LOCATION MAP



Source: U.S. Geological Survey 7.5' Northeast Pueblo topographic quadrangle - 1961 (Photorevised 1970 and 1974)