5PE.5640

COLORADO CULTURAL RESOURCE SURVEY

Architectural Inventory Form

Page 1

Official Eligil (OAHP use or	OAHP1403 Rev. 9/98	
Date	Initials	
Determine		
Determine	d Not Eligible - National Register	
Determine	d Eligible - State Register	

Determined Not Eligible - State Register Need Data

Contributing to eligible National Register District

Noncontributing to eligible National Register District



I. IDENTIFICATION

Resource number: 5PE.5640

Temporary resource number: 072 3. County: Pueblo

4. City: Pueblo

Historic building name: Johnson, J. Will, House Current building name: **Hipp-Hinders House** 7. 414 W 13th Street

Roy L. Hipp and Donna J. Hinders Owner name:

Owner organization:

Building address:

Owner address: 611 W 22nd St

National Register eligibility field assessment:

Local landmark eligibility field assessment:

Pueblo, CO 81003

☐ Individually eligible Not eligible ■ Need data Individually eligible Not eligible ■ Need data

Parcel number(s):

525418005

Pueblo North Side Neighborhood Survey Historitecture, L.L.C. * PO Box 419 Estes Park, CO 80517-0419 * (970) 586-1165 Sorted by Resource Number

414 W 13th Street 5PE.5640

(Resource number)

Architectural Inventory Form

Page 2

II. GEOGRAPHIC INFORMATION															
9.	P.M.:	6	ith			Tov	vnship):	208			R	ange:	65V	N
		SE	1/4	of	NE	1/4	of	NW	1/4	of	SE	1/4	of S	ection	25
10.	UTM	refere	ence zo	one:		13									
	Easti	ng:				53390	7					Northi	ng:		4236608
11.	USG	S qua	d nam	e:		North	east F	Pueblo	Pueblo				:		7.5
	Year: 1961 (Pho 1974)							orevis	ed 197	70 an	d				
12.	12. Lot(s): Lot 7: Blo							k 26							
	Addit	ion:				Count	ty Ado	dition				Year	of additi	on:	1869
13.	Boun	dary o	descrip	tion a	and ju	ustifica	tion:								
	The b	oound	dary, a	s des	crib	ed abo	ove, c	ontain	s but	does	not e	ceed th	e land	histori	cally associated with this property.
	Mete	es and	d boun	ds exi	ist:]								
III. A	RCHI	TEC	TUR	AL D	ES	CRIP	ΓΙΟΝ	l							
14.	14. Building plan (footprint, shape):						Irre								
	Other building plan descriptions:														
15.	Dimensions in feet (length x width):				1,8	80 sq	uare 1	feet							
16.	Number of stories:					1 1	/2								
17.	Primary external wall material(s):					Stucco Wood/Shingle						Other wall materials:			
18.	Roof	confi	guratio	n:				Otl	her Ro	oof					
	Other	r roof	config	uratio	ns:										
19.	19. Primary external roof material:						Asphalt Roof/Composition Roof								
	Other	r roof	materi	als:											
20.	Spec	ial fea	tures:					Ro	of Tre	atme	nt/Dor	mer			
								Fe	nce						
								Ch	imney	,					
								Po	rch						

21. General architectural description:

Oriented to the south, this house rests on a combination of low sandstone and concrete foundations. Light-green-painted stucco clads the exterior walls. The same color, square-cut wood shingles cover the dormers. Windows are generally 1-over-1-light, double-hung sash, with white-painted wood frames; white-painted, wood-frame screens; and dark-green-painted wood surrounds. A 3-sided, hipped-roof bay protrudes from north of center on the west elevation. Dominating the center of the front (north) façade is a large, fixed-frame window, with round-arch transom. An elaborate wood architrave surrounds the window. It features scroll brackets and 2 levels of dentil molding. A half-round, stained-glass window pierces the north end of the east elevation. Enclosing the western portion of the front, wraparound porch is a band of 15-light windows. A rounded, hipped-roof porch spans the entire façade and wraps around the northwest corner of the house. The porch features a stucco-covered kneewall and round supports. A pediment rises above the porch's easternmost quarter. The pediment features an elaborately carved bargeboard. A 4-step concrete stoop approaches the porch beneath the pediment. The principal doorway opens in the east end of the façade. It hosts a 5-panel, 1-light, oak door. The glass is beveled. It opens behind a white-painted, wood-frame screen door. Above the doorway is a single-light transom. Another doorway opens near the center of the rear (south) elevation.

Window/Stained Glass

(Resource number)

Architectural Inventory Form

Page 3

It hosts a 4-panel, white-painted wood door, opening behind and white-painted, wood-frame screen door. It provides access to a wood stoop, protected beneath a shed roof. An identical doorway-stoop combination exists on the rear (south) elevation of a hipped-roof addition to the east end of the original core's south elevation. Gray-green asphalt shingles cover the main roof and all other roof surfaces. Green-painted wood fascia and soffit box the eaves. Front-gabled dormers emerge from the east- and west-facing roof slopes. Elaborate stickwork fills the main, north-facing gable, and the gables of the dormers. An elaborately corbelled, red-brick chimney emerges between the north-facing gable and the central, hipped roof. Simpler chimneys protrude from the east elevation and near the south end of the roof ridge.

22. Architectural style: Late Victorian

Other architectural styles:

Building type:

23. Landscape or special setting features:

This property is located on terrain sloping downward from north to south, with an elevation of around 4,700 feet above mean sea level. The neighborhood features modest, one- and two-story houses. Most of the houses here have an unusually shallow setback from West 13th Street, the busy, principal east-west thoroughfare through this area. This property is situated on the south side of West 13th Street, between 412West 13th Street to the east and 416 West 13th Street to the west. A planted-grass yard, with mature landscaping, surrounds the building. Encircling a portion of the backyard is a chain-link fence. A gravel parking area is situated at the southwest corner of the lot.

24. Associated buildings, features or objects:

1: Type: Garage

Describe: A single-car garage is located on the southeast corner of the lot. Oriented to the west, the

building rests on a concrete slab. Light-green-painted stucco clads the exterior walls. The unusual garage doorway is actually located on the southwest corner of the building, with door itself folding to enclose the corner. It is of wood construction, painted light green. A window opening in the center of the south elevation has been boarded shut with light-green-painted beadboard. Gray-green asphalt shingles cover the front-gabled roof, and the rafter ends are

exposed.

IV. ARCHITECTURAL HISTORY

25. Date of Construction: Estimate: 1890 Actual:

Source of Information: Sanborn Fire Insurance Maps (for Pueblo, Colorado). New York: Sanborn Map and

Publishing Co., 1883, 1886, 1889, 1893, 1904-05, 1904-51, and 1904-52.

26. Architect: unknown

Source of information:

27. Builder: unknown

Source of information:

28. Original Owner: J. Will Johnson

Source of information: Pueblo City Directory. Pueblo, Co.; Salt Lake City; Kansas City, Mo.; and others: R.L. Polk &

Co, consulted 1886 through 2003.

29. Construction history:

According to Pueblo County Tax Assessor records, this building was constructed in 1900. However it appears on an 1893 Sanborn map. Based on those maps, this house appears to have originally been a fairly simple hipped-roof box until around 1900, when a small interior addition and large front porch were added. The rear additions also date to this time. Stucco covers the original brick wall cladding.

30. Location: original Date of move(s):

V. HISTORICAL ASSOCIATIONS

31. Original use(s): Single Dwelling32. Intermediate use(s): Single Dwelling

Pueblo North Side Neighborhood Survey
Historitecture, L.L.C. * PO Box 419
Estes Park, CO 80517-0419 * (970) 586-1165

414 W 13th Street 5PE.5640

(Resource number)

Architectural Inventory Form

Page 4

32. Intermediate use(s): Single Dwelling33. Current use(s): Business

34. Site type(s): retail business

35. Historical background:

The first owner and resident of this house, constructed around 1890, was Pueblo real estate and loan agent J. Will Johnson. He was born in December 1861 in Ohio. Around 1886 he married his wife, Clara A., who was also a native of Ohio. The young couple appears to have moved initially to Kansas, where children Edith and Frederick were born. Sometime after 1888, the family moved to Pueblo. The Johnson family resided at this house with Edith Moody, Clara's mother, and Mary Bodie, a domestic servant. The family later moved to 409 West 18th Street. J. Will Johnson died in September 1932.

Following Johnson at this address was another Pueblo entrepreneur, Walter H. Haines, proprietor of Haines Book Store at 418 North Main Street. He was born in Ohio around 1868. Around 1900 he married his wife, Lillian, and had a son, Charles. Lillian was born in Cuba. The family resided here for more than 4 decades, spanning from before 1909 through 1950.

Prior to 1960, the owner and resident was Edwin R. Porter. With his first wife, Helen Porter, Edwin had a son, Edwin L. Porter, and five daughters, Sandra Kay Porter, Lillie Bouldin, Melva Walthour, Verna Wolf, and Karen Svaldi. Helen Porter died on March 26, 1962; the elder Edwin then married Eunice Lester in 1970. Edwin R. Porter initially farmed and ranched in the Boone area. He was later a caretaker at the Citadel Health Care Center. Porter organized Pueblo's Senior Kitchen Band. He appears to have remained here through the early 1970s, when he moved to an apartment at 2104 Ogden. Edwin R. Porter died on August 10, 1987.

Soon and Sui Kwai Fong purchased the property in 1973, transferring it to Sui Kwai Fong and Roy L. Hipp in 1999. Roy Hipp and Donna J. Hinder, the current owners, acquired the house and lot in 2005. At the time of this survey, it was operated as a retail storefront.

36. Sources of information:

Pueblo County Office of Tax Assessor. Property information card [internet].

Pueblo City Directory. Pueblo, Co.; Salt Lake City; Kansas City, Mo.; and others: R.L. Polk & Co, consulted 1886 through 2003.

Sanborn Fire Insurance Maps (for Pueblo, Colorado). New York: Sanborn Map and Publishing Co., 1883, 1886, 1889, 1893, 1904-05, 1904-51, and 1904-52.

U.S. Census of 1910. Precinct 3, Pueblo, Pueblo County, Colorado. Series T624, roll 124, p. 124

U.S. Census of 1900. Precinct 1, Pueblo, Pueblo County, Colorado. Series T623, roll 128, p. 21.

"J. Will Johnson" [obituary]. Pueblo Chieftain, 29 September 1932, p. 7.

"Edwin R. Porter" [obituary]. Pueblo Chieftain, 12 August 1987, p. 6A.

5PE.5640

Architectural Inventory Form

Page 5

VI.	SIGNIFICANCE							
37	Local landmark designation: Yes No Designation authority:							
	Date of designation:							
38	. Applicable National Register criteria:							
	 A. Associated with events that have made a significant contribution to the broad pattern of our history. B. Associated with the lives of persons significant in our past. C. Embodies the distinctive characteristics of a type, period, or method of construction, or represents the work of a master, or that possess high artistic values, or represents a significant and distinguished entity whose components may lack individual distinction. D. Has yielded, or may be likely to yield, information important in history or prehistory. Qualifies under Criteria Considerations A through G (see manual). Does not meet any of the above National Register criteria. 							
	Pueblo Standards for Designation:							
	 1a. History Have direct association with the historical development of the city, state, or nation; or 1b. History Be the site of a significant historic event; or 1c. History Have direct and substantial association with a person or group of persons who had influence on society. 2a. Architecture 							
	Embody distinguishing characteristics of an architectural style or type; or							
	 2b. Architecture Be a significant example of the work of a recognized architect or master builder, or 2c. Architecture Contain elements of architectural design, engineering, materials, craftsmanship, or artistic merit which represer significant or influential innovation; 							
	 2d. Architecture Portray the environment of a group of people or physical development of an area of the city in an era of history characterized by a distinctive architectural style. 							
3a. Geography Have a prominent location or be an established, familiar, and orienting visual feature of the contemporary.								
	 3b. Geography Promote understanding and appreciation of Pueblo's environment by means of distinctive physical characteristics or rarity; or 							
	3c. Geography Make a special contribution to Pueblo's distinctive character.							
Not Applicable Does not meet any of the above Rueble landmark criteria								
	Does not meet any of the above Pueblo landmark criteria.							
3	·, ·							
4								
4	1. Level of significance: National: State Local							

(Resource number)

Architectural Inventory Form

Page 6

42. Statement of significance:

This property is historically significant under Pueblo Local Landmark criterion 1A for its association with the development of Pueblo's North Side Neighborhood, when more architecturally sophisticated buildings like this one joined the smaller, plainer dwellings originally constructed here. It is also associated with Pueblo's professional middle class, which largely settled in the neighborhood. As well, the house is architecturally significant under National Register criterion C (Pueblo Local Landmark criterion 2A) as an intact example of a Late Victorian-era style. However, the levels of architectural and historical significance, combined with physical integrity, are not to the extent that this property would qualify for individual listing in the National Register of Historic Places, the Colorado State Register of Historic Properties, or as a City of Pueblo Landmark. Nonetheless, it is most likely a contributing resource within any potential historic district.

43. Assessment of historic physical integrity related to significance:

Constructed around 1890, this house exhibits a moderately high level of physical integrity relative to the seven aspects of integrity as defined by the National Park Service and the Colorado Historical Society: location, setting, design, materials, workmanship, feeling, and association. While there have been significant structural modifications, they occurred as early as 1900, well within the period of significance. However, stucco covers the original brick exterior wall cladding, obscuring some character-defining features.

II. I	ANOITAN	L REGISTER ELIGIBILITY A	SSESSME	ENT									
44.	National R	egister eligibility field assessment:		Individu	ally eligible		No	ot el		■ Need data			
	Local landr	mark eligibility field assessment:		Individu	ally eligible	Not eligible					■ Need data		
45.	Is there Na	ational Register district potential?	Yes	No.	· •								
	Discuss:	Pueblo's North Side Neighborhood represents the evolution of the city's professional middle and upper classes. Its diversity of architectural styles and forms directly represents the city's changing economic and cultural climates. As well, the neighborhood is distinctive because it appears to have evolved independently of the area's dominant industry, steel manufacturing.											
	If there is N	National Register district potential, is t	his building	contribu	ting:	Yes	7	No		N/A			
46.	If the buildi	a:	Yes		No		N/A						

VIII. RECORDING INFORMATION

47. Photograph numbers): CD-ROM Photo Disc: North Side Photos

File Name(s): 13thstw414

Negatives filed at: Special Collections

Robert Hoag Rawlings Public Library

100 East Abriendo Avenue Pueblo, CO 81004-4290

48. Report title: Pueblo North Side Neighborhood Survey

49. Date(s): **06/22/05**

50. Recorder(s): Adam Thomas

51. Organization: Historitecture, L.L.C.

52. Address: **PO Box 419**


Estes Park, CO 80517-0419

53. Phone number(s): (970) 586-1165

414 W 13th Street 5PE.5640 (Resource number)

Architectural Inventory Form

Page 7




414 W 13th Street 5PE.5640

(Resource number)

Architectural Inventory Form

Page 8

LOCATION MAP



Source: U.S. Geological Survey 7.5' Northeast Pueblo topographic quadrangle - 1961 (Photorevised 1970 and 1974)