5PE.5644

COLORADO CULTURAL RESOURCE SURVEY

Architectural Inventory Form

Page 1

Official	Eligibility	Determination
(OAHP ı	use onlv)	

IP use only)	
--------------	--

Initials

OAHP1403

Rev. 9/98

Determined Eligible-National Register

Determined Not Eligible - National Register

Determined Eligible - State Register

Determined Not Eligible - State Register

Need Data

Date

Contributing to eligible National Register District

Noncontributing to eligible National Register District



I. IDENTIFICATION

Resource number: 5PE.5644

Temporary resource number:

3. County: **Pueblo** 4. City: **Pueblo**

Historic building name: Duke, Thomas A., House; Flutcher, Charles A. Jr.,

House

6. Current building name: Chapman, Theadus C. and Laura E., House

7. Building address: 511 W 13th Street

8. Owner name: Theadus C. & Laura E. Chapman

Owner organization:

Owner address: 511 W 13th St

Pueblo, CO 81003

National Register eligibility field assessment:

✓ Individually eligible

■ Not eligible

Parcel number(s):

525410009

■ Need data

Local landmark eligibility field assessment:

Individually eligible

■ Not eligible

Need data

(Resource number)

Architectural Inventory Form

Page 2

II. GEOGRAPHIC INFORMATION							
9.	P.M.: 6th	Township:	20\$		Rar	ige: 65	sw
	SW 1/4 of	NE 1/4 of	NW 1/4	of SE	1/4	of Section	n 25
10.	UTM reference zone:	13					
	Easting:	533828			Northing	j :	4236642
11.	USGS quad name:	Northeast Pu	ıeblo		Scale:		7.5
	Year:	1961 (Photor 1974)	evised 1970 a	and			
12.	Lot(s):	Lots 13 and	14: Block 38				
	Addition:	County Addi	tion		Year of	addition:	1869
13.	Boundary description an	nd justification:					
	The boundary, as desc	ribed above, co	ntains but do	es not ex	ceed the	land histo	rically associated with this property.
	Metes and bounds exis-	t: 🗆					
III. AI	RCHITECTURAL DE	SCRIPTION					
14.	Building plan (footprint,	shape):	Rectangula	r Plan			
	Other building plan desc	criptions:					
15.	Dimensions in feet (leng	jth x width):	1,191 squar	re feet			
16.	Number of stories:		2				
17.	Primary external wall ma	aterial(s):	Brick Wood/Shin	gle			Other wall materials:
18.	Roof configuration:		Hipped Roo	of			
	Other roof configurations	s:					
19.	Primary external roof ma	aterial:	Asphalt Ro	of/Comp	osition Ro	of	
	Other roof materials:						
20.	Special features:		Fence				
			Balcony				
			Chimney				
			Porch				

21. General architectural description:

Oriented to the south, this house rests on a high, buff-colored, rock-faced sandstone foundation arranged as coursed ashlar, with raised and beaded mortar. The basement windows are 2-light hopper and open beneath brick segmental arches. Approached by a concrete stairwell, a doorway opens in the basement, near the center of the rear (north) elevation. A protruding, dressed sandstone watertable marks the junction of the foundation and exterior walls. A khaki-painted brick veneer clads the exterior walls of the first story. Green-painted, square-cut wood shingles cover the second story. Narrow, green-painted wood siding covers an enclosed porch protruding from the west end of the east elevation. Windows are generally 1-over-1-light, double-hung sash, with green-painted wood frames. Those windows opening in brick portions of the house usually appear between sandstone sills and flat arches. Those in shingle-sided portions have cream-painted wood surrounds. Protruding from the center of the front (south) façade's first story is a 5-sided, canted bay. The bay features large, fixed-frame windows. Above the windows are rectangular panels framing swags. Windows opening in both faces of the southeast and southwest corners consist of paired, 1-light casement windows. Above them are leaded-glass transoms, with diamond-shaped glazing. Awning or hopper windows with similar glazing open in the south end of the east elevation's first story; near the

Roof Treatment/Dormer

(Resource number)

Architectural Inventory Form

Page 3

middle of the façade's second story; and in the south end of the west elevation's first story. Similarly glazed casement windows open in the hipped-roof dormer protruding from the roof's south slope. They flank a 1-over-1-light, double-hung sash window. A similar dormer protrudes from the north-facing slope. A rectangular bow window protrudes from the center of the west elevation. It corresponds to a window seat located on the landing of an interior staircase. A broad, octagonal, hipped-roof porch, following the same angles as the protruding bay, dominates the façade. Brick pedestals support the paired Doric columns. Between the pedestals is a simple wood balustrade. Approaching the porch at its center are 6 concrete steps, flaked by a wood balustrade. Urn-like finials cap the newel. More concrete steps, guarded on either side by concrete lions, lead to street level. Two doorways open on either end of the proch. The principal doorway is opens in the west side of the facade. It hosts a large, 1-panel, 1-light, oak door, with beveled glass and a large, brass knocker. The doorway on the opposite side has paired, narrow glass doors. Above the porch is an octagonal balcony. It has a simple, wood balustrade with the same newels as the front steps. It is accessed via a doorway opening in the center of the facade. It is a paneled, 1-light door, with leaded transom. An enclosed porch protrudes from the west end of the north elevation. Opening in the center of this porch is another doorway. A 4-step concrete stoop approaches the doorway. Another doorway opens above this one, proving access to a balcony above the rear porch. The balustrade is identical to the front balcony. Asphalt shingles cover the hipped roof. Khakipainted wood soffit and green-painted fascia box the broadly overhanging eaves. A dentiled cornice marks the junction of the wall and roof. A tan-painted brick chimney protrudes from the roof's west-facing slope.

While this house appears to be a Foursquare in form, the interior of the first story actually features rooms set at angles to each other.

22. Architectural style: Late 19th And 20th Century Revivals

Other architectural styles:

Building type:

23. Landscape or special setting features:

This property is located on terrain sloping downward from north to south, with an elevation of around 4,700 feet above mean sea level. The neighborhood features modest, one- and two-story houses and commercial buildings. Most of the houses here have an unusually deep setback from West 13th Street, the busy, principal east-west thoroughfare through this area. This property is situated on the north side of West 13th Street, between 1311 North Greenwood Street to the east and 515 West 13th Street to the west. A planted-grass yard, with mature landscaping, surrounds the house. Lining the west side of the property is a chain-link fence, and a tongue-and-groove wood privacy fence delimits the north edge of the parcel. Because the terrain slopes downward steeply to the south, a buff- and pink-colored, rock-faced, coursed sandstone ashlar retaining wall lines the sidewalk parallel to West 13th Street. A covered patio is located along the north edge of the property, while a concrete parking area is situated west of the garage.

24. Associated buildings, features or objects:

1: Type: Garage

Describe: A 1-car garage is located on the northeast corner of the property. Oriented to the north, the

building rests on a concrete slab. The walls consist of tan-painted bricks. Dominating the front (north) elevation is a wooden-composition, overhead-retractable garage door, painted green. A doorway opens in the south end of the west elevation. It hosts a 4-panel wood door. Appearing beneath a segmental arch, a window opening in the north end of the west elevation has been boarded shut. Asphalt sheets cover the shed roof, which a parapet surrounds on 3 sides.

IV. ARCHITECTURAL HISTORY

Date of Construction: Estimate: Actual: 1905

Source of Information: Pueblo County Office of Tax Assessor. Property information card [internet].

26. Architect: unknown

Source of information:

27. Builder: unknown

Source of information:

28. Original Owner: Thomas A. Duke

Source of information: Pueblo City Directory. Pueblo, Co.; Salt Lake City; Kansas City, Mo.; and others: R.L. Polk &

Co, consulted 1886 through 2003.

(Resource number)

Architectural Inventory Form

Page 4

29. Construction history:

According to Pueblo County Tax Assessor records, this building was constructed in 1905. Sanborn maps and city directories corroborate this date. The only notable structural alteration has been the addition of the enclosed porch on the west end of the north elevation, which occurred prior to 1952. The windows in the canted bay projecting from the center of the façade's first story appear to have been replaced. This house underwent a restoration around 2000.

30. Location: **original** Date of move(s):

V. HISTORICAL ASSOCIATIONS

31. Original use(s): Single Dwelling
32. Intermediate use(s): Single Dwelling
33. Current use(s): Single Dwelling
34. Site type(s): Residence

35. Historical background:

This house was constructed in 1905 for prominent Pueblo merchant Thomas Alexander Duke, co-owner of the Henkel-Duke Mercantile Company, a wholesale grocer. Duke was born on December 8, 1875, in Colorado. His wife, Vinnie D. Duke, was born in Iowa in April 1875. They were married in 1900. Before the construction of their West 13th Street residence, the Dukes lived at 1415 Craig Street. After their move, they generally resided here with a maid who, in 1910, was Essie Roberts. The couple had a daughter, Clara May Soule. The Dukes lived here through 1935, later residing at 2500 North Elizabeth Street.

Prior to 1940, the owner and resident was Charles A. Flutcher, Jr., who remained here until his death nearly 4 decades later. He graduated from the University of Illinois and eventually became president of the Colorado Laundry in Pueblo and the Pearl Laundry in Colorado Springs. He later was a real estate agent, associated with the Rowland Realty Company. He served on Pueblo County School Board No. 1 and was a member of the Parkview Episcopal Hospital Board of Trustees. With his wife, Doris Flutcher, Charles had a son and a daughter, Charles A Flutcher, III, and Doralee Miller. The elder Charles Flutcher died on December 22, 1978. His widow, Doris, remained here through at least 1993. Her daughter, Doralee Miller, sold the property to Kermit R. Clay in 1994. Theadus C. and Laura E. Chapmen, the current owners and residents, purchased the house and lot from Clay in 2003.

36. Sources of information:

Pueblo County Office of Tax Assessor. Property information card [internet].

Pueblo City Directory. Pueblo, Co.; Salt Lake City; Kansas City, Mo.; and others: R.L. Polk & Co, consulted 1886 through 2003.

Sanborn Fire Insurance Maps (for Pueblo, Colorado). New York: Sanborn Map and Publishing Co., 1883, 1886, 1889, 1893, 1904-05, 1904-51, and 1904-52.

"Duke (Thomas A.)" [obituary]. Pueblo Chieftain, 2 September 1949, p. 12.

"Charles A. Flutcher, Jr." [obituary]. Pueblo Chieftain, 24 December 1978, p. 8B.

Chapman, Theadus C. Interview with Adam Thomas, 22 June 2005.

U.S. Census of 1910. Precinct 3, Pueblo, Pueblo County, Colorado. Series T624, roll 124, p. 124

U.S. Census of 1900. Precinct 1, Pueblo, Pueblo County, Colorado. Series T623, roll 128, p. 15.

(Resource number)

Architectural Inventory Form

Page 5

ı. S	GNIFICANCE
37.	Local landmark designation: Yes No
	Designation authority:
	Date of designation:
38.	Applicable National Register criteria:
	A. Associated with events that have made a significant contribution to the broad pattern of our history. B. Associated with the lives of persons significant in our past. C. Embodies the distinctive characteristics of a type, period, or method of construction, or represents the work of a master, or that possess high artistic values, or represents a significant and distinguished entity whose components may lack individual distinction. D. Has yielded, or may be likely to yield, information important in history or prehistory. Qualifies under Criteria Considerations A through G (see manual). Does not meet any of the above National Register criteria.
	1a. HistoryHave direct association with the historical development of the city, state, or nation; or1b. History
	Be the site of a significant historic event; or
	1c. History Have direct and substantial association with a person or group of persons who had influence on society.
	2a. ArchitectureEmbody distinguishing characteristics of an architectural style or type; or
	2b. Architecture
	Be a significant example of the work of a recognized architect or master builder, or
	 2c. Architecture Contain elements of architectural design, engineering, materials, craftsmanship, or artistic merit which represent a significant or influential innovation;
	2d. Architecture
	Portray the environment of a group of people or physical development of an area of the city in an era of history characterized by a distinctive architectural style.
	3a. Geography
	Have a prominent location or be an established, familiar, and orienting visual feature of the contemporary city, or
	3b. Geography Promote understanding and appreciation of Pueblo's environment by means of distinctive physical characteristics or rarity; or
	3c. Geography Make a special contribution to Pueblo's distinctive character.
	Not Applicable Does not meet any of the above Pueblo landmark criteria.
39.	Area(s) of Significance: Social History Architecture
40.	Period of Significance: Social History, 1905-1955; Architecture, 1905
41.	Level of significance: National: State Local

(Resource number)

Architectural Inventory Form

Page 6

42. Statement of significance:

This property is significant under National Register Criterion A (Pueblo Local Landmark Criterion 1A--history) for its association with the development of Pueblo's North Side Neighborhood, when more architecturally sophisticated buildings like this one joined the smaller, plainer dwellings originally constructed here. It is also associated with Pueblo's professional, entrepreneurial middle class, which largely settled in the neighborhood. This house has been home to two prominent Pueblo merchants, Thomas Duke and Charles Flutcher Jr. Thus, this building is also significant under Pueblo Local Landmark Criterion 1C (important individuals) for its association with Duke and Flutcher, both of whom were business and civic leaders. As well, the house is significant under National Register Criterion C (Local Landmark Criterion 2A--architecture) as a classically styled dwelling with many unusual architectural features, including the three-sided porch and bay, corner windows, and angular interior floor plan. Character-defining classical features include the Doric columns and pilasters, dentiled cornice, and newel posts with finials. The levels of architectural and historical significance, combined with physical integrity, are to the extent that this property could potentially qualify for individual listing in the National Register of Historic Places, the Colorado State Register of Historic Properties, or as a City of Pueblo Landmark. It is most likely a contributing resource within any potential historic district.

43. Assessment of historic physical integrity related to significance:

Constructed in 1905, this house exhibits a moderately high level of physical integrity relative to the seven aspects of integrity as defined by the National Park Service and the Colorado Historical Society: location, setting, design, materials, workmanship, feeling, and association. The only notable alteration has been the construction of the small, rear (north) porch, which occurred within the period of significance. As well, portions of the windows in the façade's first-story canted bay may have been replaced. Nonetheless, this property certainly retains sufficient physical integrity to convey its architectural and historical significance.

∕II.	NATIONAI	L REGISTER ELIGIBILITY A	SSESSMENT									
44.	National Re	egister eligibility field assessment:	Individually eligible			■ Not eligible					l data	
	Local landn	nark eligibility field assessment:	Individua	Not eligible				Need data				
45.	Is there National Register district potential?		Yes 🚁 No									
	Discuss: Pueblo's North Side Neighborhood represents the evolution of the city's professional middle and upper classes. Its diversity of architectural styles and forms directly represents the city's changing economic and cultural climates. As well, the neighborhood is distinctive because it appears to have evolved independently the area's dominant industry, steel manufacturing.											
	If there is N	lational Register district potential, is t	his building contributi	ing:	Yes	No		N/A				
46.	If the building	ng is in existing National Register dis	trict, is it contributing	:	Yes	No		N/A				

VIII. RECORDING INFORMATION

47.	Photograph numbers):	CD-ROM Photo Disc: North Side Photos
		File Name(s): 13thstw511

Negatives filed at: Special Collections

Robert Hoag Rawlings Public Library

100 East Abriendo Avenue Pueblo, CO 81004-4290

48. Report title: Pueblo North Side Neighborhood Survey

49. Date(s): **06/22/05**

50. Recorder(s): Adam Thomas

51. Organization: Historitecture, L.L.C.

52. Address: **PO Box 419**


Estes Park, CO 80517-0419

53. Phone number(s): (970) 586-1165

511 W 13th Street 5PE.5644 (Resource number)

Architectural Inventory Form

Page 7




(Resource number)

Architectural Inventory Form

Page 8

LOCATION MAP



Source: U.S. Geological Survey 7.5' Northeast Pueblo topographic quadrangle - 1961 (Photorevised 1970 and 1974)