

COLORADO CULTURAL RESOURCE SURVEY

Architectural Inventory Form

Page 1

- Date _____ Initials _____
- ___ Determined Eligible-National Register
 - ___ Determined Not Eligible - National Register
 - ___ Determined Eligible - State Register
 - ___ Determined Not Eligible - State Register
 - ___ Need Data
 - ___ Contributing to eligible National Register District
 - ___ Noncontributing to eligible National Register District



I. IDENTIFICATION

- 1. Resource number: **5PE.5645** Parcel number(s):
- 2. Temporary resource number: **076** **525410008**
- 3. County: **Pueblo**
- 4. City: **Pueblo**
- 5. Historic building name: **Nash, Herman Woodworth, House**
- 6. Current building name: **Archuleta, Jimmy R. and Diana, House**
- 7. Building address: **515 W 13th Street**
- 8. Owner name: **Jimmy R. and Diana Archuleta**
- Owner organization:
- Owner address: **515 W 13th St**
Pueblo, CO 81003

44. National Register eligibility field assessment:	<input type="checkbox"/> Individually eligible	<input checked="" type="checkbox"/> Not eligible	<input type="checkbox"/> Need data
Local landmark eligibility field assessment:	<input checked="" type="checkbox"/> Individually eligible	<input checked="" type="checkbox"/> Not eligible	<input checked="" type="checkbox"/> Need data

Architectural Inventory Form

Page 2

II. GEOGRAPHIC INFORMATION

9. P.M.: **6th** Township: **20S** Range: **65W**
SW 1/4 of **NE** 1/4 of **NW** 1/4 of **SE** 1/4 of Section **25**
10. UTM reference zone: **13**
Easting: **533803** Northing: **4236644**
11. USGS quad name: **Northeast Pueblo** Scale: **7.5**
Year: **1961 (Photorevised 1970 and 1974)**
12. Lot(s) : **Lot 12: Block 38**
Addition: **County Addition** Year of addition: **1869**
13. Boundary description and justification:
The boundary, as described above, contains but does not exceed the land historically associated with this property.
Metes and bounds exist:

III. ARCHITECTURAL DESCRIPTION

14. Building plan (footprint, shape): **Irregular Plan**
Other building plan descriptions:
15. Dimensions in feet (length x width): **1,005 square feet**
16. Number of stories: **1**
17. Primary external wall material(s): **Synthetics/Vinyl** Other wall materials:
18. Roof configuration: **Gabled Roof/Cross Gabled Roof**
Other roof configurations:
19. Primary external roof material: **Asphalt Roof/Composition Roof**
Other roof materials:
20. Special features: **Fence**
Chimney
Porch
21. General architectural description:
Oriented to the south, this house rests on a foundation entirely concealed behind cream-colored vinyl siding. The same vinyl siding, with tan vinyl cornerboards, clads the exterior walls. Tan, vertically oriented siding covers the gables. Windows are generally 6-over-1-light, double-hung sash, with cream-painted wood frames and brown, aluminum-frame storm windows. All windows have tan, vinyl surrounds. The east end of the front (south) elevation hosts a single-light picture window. Another picture window pierces the north end of the east elevation. The south end of the same elevation has a single-light hopper or awning window. A shed-roofed porch extends across the eastern half of the front (south) façade. It has a concrete floor and simple, tan-painted supports. Concrete steps approach on the west side of the north elevation and at its east end. The principal doorway opens near the center of the asymmetrical façade. It hosts a white, 4-panel metal door, with fanlight. Gray-green asphalt shingles cover the cross-gabled roof, and the eaves are boxed with cream vinyl soffit and tan vinyl fascia. The east-facing gable is clipped. An engaged hearth and chimney, also covered in vinyl siding, protrudes south of center on the east elevation.
22. Architectural style: **No Style**
Other architectural styles:

Architectural Inventory Form

Page 3

Building type:

23. Landscape or special setting features:

This property is located on terrain sloping downward from north to south, with an elevation of around 4,700 feet above mean sea level. The neighborhood features modest, one- and two-story houses and commercial buildings. Most of the houses here have an unusually deep setback from West 13th Street, the busy, principal east-west thoroughfare through this area. This property is situated on the north side of West 13th Street, between 511 West 13th Street to the east and 1300 North Elizabeth Street to the west. A planted-grass yard, with mature landscaping, surrounds the house. Lining much of the property is a chain-link. A random-coursed sandstone retaining wall lines the sidewalk parallel to West 13th Street. Because the property immediately west is at street level, a massive concrete retaining wall delimits the western edge of the property.

24. Associated buildings, features or objects:

1: Type: **Garage**

Describe: **A 2-car garage is located north of the house, on the northern edge of the property. Oriented to the west, the building rests on a concrete slab. Cream-colored vinyl siding clads the exterior walls. Covering the gables is tan, vertically oriented vinyl siding. Offset north of center in the front (west) elevation is a 32-panel, steel, overhead-retractable garage door, painted white. Gray-green asphalt shingles cover the front-gabled roof, and vinyl boxes the eaves.**

IV. ARCHITECTURAL HISTORY

25. Date of Construction: Estimate: Actual: **1926**Source of Information: **Pueblo County Office of Tax Assessor. Property information card [internet].**26. Architect: **unknown**

Source of information:

27. Builder: **unknown**

Source of information:

28. Original Owner: **Herman Woodworth Nash**Source of information: **Pueblo City Directory. Pueblo, Co.; Salt Lake City; Kansas City, Mo.; and others: R.L. Polk & Co, consulted 1886 through 2003.**

29. Construction history:

According to Pueblo County Tax Assessor records, this building was constructed in 1926. Sanborn maps and city directories corroborate this date. A front-gabled addition was made to the rear elevation, sometime after 1952. The original porch and windows have been replaced within the last 10 years (1995-2005). Also, the owners installed vinyl siding, probably at the same time.

30. Location: **original** Date of move(s):

V. HISTORICAL ASSOCIATIONS

31. Original use(s): **Single Dwelling**32. Intermediate use(s): **Single Dwelling**33. Current use(s): **Single Dwelling**34. Site type(s): **Residence**

35. Historical background:

The first owner and resident of this house, constructed in 1926, was Pueblo pioneer Herman Woodworth Nash. He was born in New York in December 1857. He settled in Pueblo in 1878. Around 1892 he married his wife, Emma S., who was born in Ohio in November 1866. They had a son, Irving, born in October 1893. Herman Nash was a court reporter in Pueblo for more than 50 years. He died in this house on August 12, 1943. Emma remained her until her own death, also in this house, on November 8, 1948.

Architectural Inventory FormPage 4

Following Emma Nash's death, the owner and resident of this property was Carl E. Hanson, a civil engineer. He remained here through 1955. Jimmy R. and Diana Archuleta, the current owners and residents, purchased this property in 1974

36. Sources of information:

Pueblo County Office of Tax Assessor. Property information card [internet].

Pueblo City Directory. Pueblo, Co.; Salt Lake City; Kansas City, Mo.; and others: R.L. Polk & Co, consulted 1886 through 2003.

Sanborn Fire Insurance Maps (for Pueblo, Colorado). New York: Sanborn Map and Publishing Co., 1883, 1886, 1889, 1893, 1904-05, 1904-51, and 1904-52.

"Nash (Herman Woodworth)" [obituary]. Pueblo Chieftain, 13 August 1943, p. 5.

"Nash (Emma Smith)" [obituary]. Pueblo Chieftain, 9 November 1948, p. 2.

U.S. Census of 1910. Precinct 3, Pueblo, Pueblo County, Colorado. Series T624, roll 124, p. 122.

u.s. census of 1900. Ward 6, Pueblo, Pueblo County, Colorado. Series T623, roll 128, p. 220.

Architectural Inventory Form

Page 5

VI. SIGNIFICANCE

37. Local landmark designation: Yes No

Designation authority:

Date of designation:

38. Applicable National Register criteria:

- A. Associated with events that have made a significant contribution to the broad pattern of our history.
- B. Associated with the lives of persons significant in our past.
- C. Embodies the distinctive characteristics of a type, period, or method of construction, or represents the work of a master, or that possess high artistic values, or represents a significant and distinguished entity whose components may lack individual distinction.
- D. Has yielded, or may be likely to yield, information important in history or prehistory.
- Qualifies under Criteria Considerations A through G (see manual).
- Does not meet any of the above National Register criteria.

Pueblo Standards for Designation:1a. History Have direct association with the historical development of the city, state, or nation; or1b. History Be the site of a significant historic event; or1c. History Have direct and substantial association with a person or group of persons who had influence on society.2a. Architecture Embody distinguishing characteristics of an architectural style or type; or2b. Architecture Be a significant example of the work of a recognized architect or master builder, or2c. Architecture Contain elements of architectural design, engineering, materials, craftsmanship, or artistic merit which represent a significant or influential innovation;2d. Architecture Portray the environment of a group of people or physical development of an area of the city in an era of history characterized by a distinctive architectural style.3a. Geography Have a prominent location or be an established, familiar, and orienting visual feature of the contemporary city, or3b. Geography Promote understanding and appreciation of Pueblo's environment by means of distinctive physical characteristics or rarity; or3c. Geography Make a special contribution to Pueblo's distinctive character.Not Applicable Does not meet any of the above Pueblo landmark criteria.39. Area(s) of Significance: **Not Applicable**40. Period of Significance: **n/a**41. Level of significance: National: State Local

Architectural Inventory Form

Page 6

42. Statement of significance:

This property is historically significant under Pueblo Local Landmark criterion 1A for its association with the development of Pueblo's North Side Neighborhood, when more architecturally sophisticated buildings like this one joined the smaller, plainer dwellings originally constructed here. However, the levels of architectural and historical significance, combined with physical integrity, are not to the extent that this property would qualify for individual listing in the National Register of Historic Places, the Colorado State Register of Historic Properties, or as a City of Pueblo Landmark. It should not be considered a contributing resource within any potential historic district.

43. Assessment of historic physical integrity related to significance:

Constructed in 1926, this house exhibits a low level of physical integrity relative to the seven aspects of integrity as defined by the National Park Service and the Colorado Historical Society: location, setting, design, materials, workmanship, feeling, and association. Additions and replacements have altered the original form and concealed or removed critical character-defining features. This building does not retain sufficient physical integrity to convey its architectural or historical significance.

VII. NATIONAL REGISTER ELIGIBILITY ASSESSMENT

44. National Register eligibility field assessment: Individually eligible Not eligible Need data
Local landmark eligibility field assessment: Individually eligible Not eligible Need data
45. Is there National Register district potential? Yes No
Discuss: **Pueblo's North Side Neighborhood represents the evolution of the city's professional middle and upper classes. Its diversity of architectural styles and forms directly represents the city's changing economic and cultural climates. As well, the neighborhood is distinctive because it appears to have evolved independently of the area's dominant industry, steel manufacturing.**
- If there is National Register district potential, is this building contributing: Yes No N/A
46. If the building is in existing National Register district, is it contributing: Yes No N/A

VIII. RECORDING INFORMATION

47. Photograph numbers): **CD-ROM Photo Disc: North Side Photos
File Name(s): 13thstw515**
- Negatives filed at: **Special Collections
Robert Hoag Rawlings Public Library
100 East Abriendo Avenue
Pueblo, CO 81004-4290**
48. Report title: **Pueblo North Side Neighborhood Survey**
49. Date(s): **06/22/05**
50. Recorder(s): **Adam Thomas**
51. Organization: **Historitecture, L.L.C.**
52. Address: **PO Box 419
Estes Park, CO 80517-0419**
53. Phone number(s): **(970) 586-1165**


Architectural Inventory Form

SITE SKETCH MAP



Architectural Inventory Form

LOCATION MAP



Source: U.S. Geological Survey 7.5' Northeast Pueblo topographic quadrangle - 1961 (Photorevised 1970 and 1974)