

COLORADO CULTURAL RESOURCE SURVEY

Architectural Inventory Form

Page 1

- Date _____ Initials _____
- ___ Determined Eligible-National Register
- ___ Determined Not Eligible - National Register
- ___ Determined Eligible - State Register
- ___ Determined Not Eligible - State Register
- ___ Need Data
- ___ Contributing to eligible National Register District
- ___ Noncontributing to eligible National Register District



I. IDENTIFICATION

- 1. Resource number: **5PE.5650** Parcel number(s):
- 2. Temporary resource number: **525409006**
- 3. County: **Pueblo**
- 4. City: **Pueblo**
- 5. Historic building name: **Housing Authority of Pueblo Apartments**
- 6. Current building name: **Housing Authority of Pueblo Apartments**
- 7. Building address: **615-619 W 13th Street**
- 8. Owner name: **Housing Authority of Pueblo**
- Owner organization:
- Owner address: **1414 N Santa Fe Ave**
Pueblo, CO 81003

44. National Register eligibility field assessment:	<input type="checkbox"/> Individually eligible	<input checked="" type="checkbox"/> Not eligible	<input type="checkbox"/> Need data
Local landmark eligibility field assessment:	<input checked="" type="checkbox"/> Individually eligible	<input checked="" type="checkbox"/> Not eligible	<input checked="" type="checkbox"/> Need data

Architectural Inventory Form

Page 2

II. GEOGRAPHIC INFORMATION

9. P.M.: **6th** Township: **20S** Range: **65W**
SW 1/4 of **NW** 1/4 of **NW** 1/4 of **SE** 1/4 of Section **25**
10. UTM reference zone: **13**
 Easting: **533666** Northing: **4236651**
11. USGS quad name: **Northeast Pueblo** Scale: **7.5**
 Year: **1961 (Photorevised 1970 and 1974)**
12. Lot(s) : **Easterly 36 feet of Lot 11 and all of Lot 12; Block 41**
 Addition: **County Addition** Year of addition: **1869**
13. Boundary description and justification:
The boundary, as described above, contains but does not exceed the land historically associated with this property.
 Metes and bounds exist:

III. ARCHITECTURAL DESCRIPTION

14. Building plan (footprint, shape): **Irregular Plan**
 Other building plan descriptions:
15. Dimensions in feet (length x width): **1,500 square feet**
16. Number of stories: **1**
17. Primary external wall material(s): **Brick** Other wall materials:
Stucco
18. Roof configuration: **Gabled Roof/Front Gabled Roof**
 Other roof configurations:
19. Primary external roof material: **Asphalt Roof/Composition Roof**
 Other roof materials:
20. Special features: **Fence**
Porch
21. General architectural description:
Oriented to the south, this triplex rests on a concrete foundation. A brown-brick veneer clads the exterior walls. Tan stucco covers the gables. Windows are 1-beside-1-light, sliding-sash, with aluminum-frames. They open above brick sills. Doorways open in the south elevation of gabled wings projecting from near the centers of the east and west elevations. Another opens in the west elevation of a hipped-roof structure protruding from the center of the front (south) façade. These doorways provide access to the units addressed (from east to west) 615, 617, and 619 West 13th Street. Each hosts a tan-painted, 6-panel metal door, opening behind an aluminum-frame storm door. Low concrete stoops, flanked by tan-painted pipe railings, approach each of the doorways. Three sets of sliding, plate-glass doors open across the rear (north) elevation. The easternmost and westernmost doorways open in projecting, front-gabled structures. A shallow pent roof shelters the middle doorway. All 3 provide access to concrete patios. Brown-gray asphalt shingles cover the main, front-gabled roof and all other roof structures. Boxing the eaves are brown-painted wood fascia and soffit.
22. Architectural style: **No Style**
 Other architectural styles:
 Building type:
23. Landscape or special setting features:

Architectural Inventory Form

Page 3

This property is located on terrain sloping downward from north to south, with an elevation of around 4,700 feet above mean sea level. The neighborhood features modest, one- and two-story houses and commercial buildings. Setbacks from West 13th Street, the busy, principal east-west thoroughfare through this area, vary widely on this block. A grass-covered strip separates West 13th Street, the busy, principal east-west thoroughfare through this area, from the sidewalk. This property is situated on the north side of West 13th Street, between 611 West 13th Street to the east and 1302 West Street to the west. The unusually deep setback from the street accommodates a macadam parking lot in front (south of) the building. Planted grass covers the backyard, which a chain-link fence surrounds. A concrete retaining wall runs along the alley behind (north of) the property.

24. Associated buildings, features or objects: **No associated buildings identified.**

IV. ARCHITECTURAL HISTORY

25. Date of Construction: Estimate: Actual: **1982**
 Source of Information: **Pueblo County Office of Tax Assessor. Property information card [internet].**
26. Architect: **unknown**
 Source of information:
27. Builder: **unknown**
 Source of information:
28. Original Owner: **Housing Authority of Pueblo**
 Source of information: **Pueblo County Office of Tax Assessor. Property information card [internet].**
29. Construction history:
According to Pueblo County Tax Assessor records, this building was constructed in 1982. It has not been altered since its construction.
30. Location: **original** Date of move(s):

V. HISTORICAL ASSOCIATIONS

31. Original use(s): **Multiple Dwelling**
32. Intermediate use(s): **Multiple Dwelling**
33. Current use(s): **Multiple Dwelling**
34. Site type(s): **Apartments**
35. Historical background:
The Housing Authority of Pueblo purchased this formerly vacant parcel from Samuel E. Nelson in May 1981. The authority completed the current apartment building in 1982.
36. Sources of information:
Pueblo County Office of Tax Assessor. Property information card [internet].
Sanborn Fire Insurance Maps (for Pueblo, Colorado). New York: Sanborn Map and Publishing Co., 1883, 1886, 1889, 1893, 1904-05, 1904-51, and 1904-52.

Architectural Inventory Form

Page 4

VI. SIGNIFICANCE

37. Local landmark designation: Yes No

Designation authority:

Date of designation:

38. Applicable National Register criteria:

- A. Associated with events that have made a significant contribution to the broad pattern of our history.
- B. Associated with the lives of persons significant in our past.
- C. Embodies the distinctive characteristics of a type, period, or method of construction, or represents the work of a master, or that possess high artistic values, or represents a significant and distinguished entity whose components may lack individual distinction.
- D. Has yielded, or may be likely to yield, information important in history or prehistory.
- Qualifies under Criteria Considerations A through G (see manual).
- Does not meet any of the above National Register criteria.

Pueblo Standards for Designation:1a. History Have direct association with the historical development of the city, state, or nation; or1b. History Be the site of a significant historic event; or1c. History Have direct and substantial association with a person or group of persons who had influence on society.2a. Architecture Embody distinguishing characteristics of an architectural style or type; or2b. Architecture Be a significant example of the work of a recognized architect or master builder, or2c. Architecture Contain elements of architectural design, engineering, materials, craftsmanship, or artistic merit which represent a significant or influential innovation;2d. Architecture Portray the environment of a group of people or physical development of an area of the city in an era of history characterized by a distinctive architectural style.3a. Geography Have a prominent location or be an established, familiar, and orienting visual feature of the contemporary city, or3b. Geography Promote understanding and appreciation of Pueblo's environment by means of distinctive physical characteristics or rarity; or3c. Geography Make a special contribution to Pueblo's distinctive character.Not Applicable Does not meet any of the above Pueblo landmark criteria.39. Area(s) of Significance: **Not Applicable**40. Period of Significance: **n/a**41. Level of significance: National: State Local

Architectural Inventory Form

Page 5

42. Statement of significance:

Because this property is less than 50 years old and does not meet any of criteria considerations A through G, it is ineligible for listing in the National Register of Historic Places. Moreover, the architectural and historical significance are not to the extent that the property would qualify for individual listing in the Colorado State Register of Historic Properties or as a City of Pueblo landmark. Given its age, the property should not be considered a contributing resource within any potential historic district.

43. Assessment of historic physical integrity related to significance:

Constructed in 1982, this house exhibits a high level of physical integrity relative to the seven aspects of integrity as defined by the National Park Service and the Colorado Historical Society: location, setting, design, materials, workmanship, feeling, and association. It has not been altered since its construction.

VII. NATIONAL REGISTER ELIGIBILITY ASSESSMENT

44. National Register eligibility field assessment: Individually eligible Not eligible Need data
 Local landmark eligibility field assessment: Individually eligible Not eligible Need data
45. Is there National Register district potential? Yes No
- Discuss: **Pueblo's North Side Neighborhood represents the evolution of the city's professional middle and upper classes. Its diversity of architectural styles and forms directly represents the city's changing economic and cultural climates. As well, the neighborhood is distinctive because it appears to have evolved independently of the area's dominant industry, steel manufacturing.**
- If there is National Register district potential, is this building contributing: Yes No N/A
46. If the building is in existing National Register district, is it contributing: Yes No N/A

VIII. RECORDING INFORMATION

47. Photograph numbers): **CD-ROM Photo Disc: North Side Photos
File Name(s): 13thstw615-619**
- Negatives filed at: **Special Collections
Robert Hoag Rawlings Public Library
100 East Abriendo Avenue
Pueblo, CO 81004-4290**
48. Report title: **Pueblo North Side Neighborhood Survey**
49. Date(s): **06/27/05**
50. Recorder(s): **Adam Thomas**
51. Organization: **Historitecture, L.L.C.**
52. Address: **PO Box 419
Estes Park, CO 80517-0419**
53. Phone number(s): **(970) 586-1165**

Architectural Inventory Form


Page 6

SITE SKETCH MAP



Architectural Inventory Form

LOCATION MAP



Source: U.S. Geological Survey 7.5' Northeast Pueblo topographic quadrangle - 1961 (Photorevised 1970 and 1974)